

in Kuwait. Soldiers

were conducting

simulated training

on a range when

one Soldier's

weapon, round

that struck another

Soldier in the calf.

**COST: 1 Soldier Injured** 



## SOLDIERS DIED IN ACCIDENTS

2 Soldiers injured

• 2 M1114 HMMWV Damaged

## LOSSES

→ A Soldier died Sept. 23 as a result of injuries sustained in a motorcycle accident Sept. 15 at 2020 local in Von Ormy, Texas. The Soldier was operating a 2006 Harley Dyna Glide and failed to yield to a merging Jeep. He attended a motorcycle safety training course. The Soldier was not wearing a helmet.

**COST: 1 Soldier Killed** 

► A Soldier was injured in a single Army motor vehicle rollover accident Sept. 19 at 1900 local in Iraq. The Soldier was the gunner in an M1114 HMMWV that went off

## the road and rolled. **COST: 1 Soldier Injured** 1 M1114 HMMWV **Damaged**

► A Soldier was killed in an M1114 HMMWV rollover accident Sept. 19 at 2100 local in Iraq. The Soldier was the vehicle commander during a mission. As the driver of the HMMWV turned onto a narrow road, the vehicle went off the road and rolled into a canal, trapping and drowning the Soldier. **COST: 1 Soldier Killed 1 M1114 HMMWY Damaged** 

Two Soldiers were killed in an AH-64D

Apache helicopter crash Sept. 19 at 2240 local in Grafenwoehr. Germany. The pilot and the co-pilot/gunner were conducting diving rocket fire during a night aerial gunnery range operation. The aircraft did not pull up from a dive after engaging a target and impacted the ground. The two Soldiers died, and the aircraft was destroyed in a post-crash fire. The U.S. Army Combat Readiness Center is investigating the accident.

**COST: 2 Soldiers Killed** 1 AH-64D Destroyed

